

CASPIR Aircraft Accident Cards

Serial: FE316

Title: North American Harvard Mk. IIB serial:FE316 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-18. Harvard II s/n FE316. This accident involved 1 person. Thompson R

Keywords: RAFHarvard II,FE316,41 SFTS,41 Service Flying Training School,Weyburn Aerodrome,1942-August-18,ThompsonRCAF L20

Created: 1942-08-18

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE316>

DUTY ON WHICH ENGAGED:

Steep turns and aerobatics.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Ground loop. Aircraft swung and buried nose in runway.

DATE:

COMPOSITION:

LS / ANT / PSS / PCM / ✓

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

~~Inexperience of pilot.~~

2. Sweung

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C swung on landing, brakes applied, tail left ground and nose went into runway.~~

RECORDED BY

DATE

CHECKED BY

DATE