



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

**Solo night landings.**

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**R.170**

**Pilot states STBD engine failed while carrying out normal overshoot procedure, pilot cut port engine and crashed through airdrome boundary into a ravine.**

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~STBD engine failure.~~

*15. Forced Land.*

**15**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Nil**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

*26. Engine trouble. Accidents*

**26**

RECORDED BY

DATE

CHECKED BY

DATE