

CASPIR Aircraft Accident Cards

Serial: 8219

Title: Avro Anson Mk. II serial:8219 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-23. Anson II s/n 8219. This accident involved 3 people. Gover TE, Machin LW, Whitton LM

Keywords: RAFAnson II,8219,31 BGS,31 Bomb & Gunnery School,Aerodrome,1942-August-23,Gover,Machin,WhittonRCAF L20

Created: 1942-08-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8219>

DUTY ON WHICH ENGAGED:

Bombing training exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Overshooting on landing, pilot opened up engines too late and collided with airdrome boundary.

DATE:

B.170

COMPOSITION:

10/1/50

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

~~Failure of flaps to lower causing pilot to touch down half way down runway.~~

1. Overshoot.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Error of Judgment."

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Error of judgment of pilot in that he made his landing approach to far down runway and failed to open up his engines in time to make another circuit.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____