

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT		OTHERS										AIRFRAME FAILURE										ENGINE FAILURE									
CAUSES OF ACCIDENTS																															
UNIT		COM.		PLACE												DATE		TIME													
132 (F) SQDN. Patricia Bay		WAC		On taxi strip just North of No. 5 hanger.												23-8-42		1540													
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT		H.O. FILE																	
Kittyhawk		AL216		C 1		x		x		x		x		1300-AL216																	
NAME			RANK		No.		DUTY		INJURIES										SERIOUS												
Elliott G.J.			F/L		CL349		P.		Uninjured.										FATAL INJURY												
																CARD SERIAL No.															
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																			
Kittyhawk		AL216		Slight								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS													
Allison		Not Known		Nil								65 35		- 75		86 800															
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																	
A-534		23-8-42																													
NATURE OF ACCIDENT																															

MISCELLANEOUS CAUSES
 STAGE OF FLIGHT

HAND Q.
 INSTS.
 WEATHER
 DRAINS.
 AL G SURF.
 OTHER
 UND TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STRATY
 FATAL
 INJ.
 INJURY

18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

DUTY ON WHICH ENGAGED:

Testing new aircraft.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Tail raised causing propellor to strike ground damaging tips while pilot endeavouring to caster tail wheel to pilots left. Left brake wheel caster faulty. Pilot was using throttle to swing A/C to left in high wind.

7/1/41/100/1000

RECOMMENDATIONS:

PRIMARY CAUSE:

Faulty brakes.

J. Othello

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

tail wheel caster faulty.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____