

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	4089
<b>Title:</b>	de Havilland Moth, Tiger I serial:4089 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1942-August-12. Tiger Moth s/n 4089. This accident involved 1 person. Russell WJ
<b>Keywords:</b>	RCAFTiger Moth ,4089,15 EFTS,15 Elementary Flying Training School,Aerodrome,1942-August-12,RussellRCAF L20
<b>Created:</b>	1942-08-12
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#4089">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#4089</a>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Circuits and landings.

OR COMMANDING OFFICER'S REPORT:

**R.170**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

*LH/1547/USA*

Ballooned on landing opened throttle but had insufficient speed to sustain flight resulting in heavy landing and collapsing of undercarriage.

RECOMMENDATIONS:

*nil*

PRIMARY CAUSE:

Aircraft ballooned on landing.

*H. Heavy*

*(H)*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*nil*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Heavy landing caused landing gear failure.

*(3/16)*

*34 up stream*

RECORDED BY

DATE

CHECKED BY

DATE