

TYPE OF A/C	CAUSES OF ACCIDENTS										MISCELLANEOUS																												
	PILOT					OTHERS					AIRFRAME FAILURE					ENGINE FAILURE					MISCELLANEOUS																		
UNIT	32 E.F.T S. Bowden, Alberta										COM. # 4		PLACE Main Aerodrome								DATE 17-8-42		TIME 1700		HANDO.														
A/C TYPE	Stearman										No. FJ894		CRASH CAT. C		SE x		ME x		DAY x		NIGHT		INSTS.																
NAME	Rooney, T.										RANK LAC		No. R929276				DUTY PP		INJURIES Uninjured.				SERIOUS		DRKNS.														
TYPE OF ENGINE	TYPE A/F & ENGINE										No. FJ894		EXTENT OF DAMAGE Slight		REPORT FORM		SERIAL No.		DATE		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.		ALG SURF.								
CATEGORY	Contl. 52731										Nil												DUAL		SOLO		18		OTHER										
SIGNAL No. & DATE	A 267 18-8										UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		UNDTD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG STR.		AIRSCREW A.		ENG. CONTS.		MISCEL.
NATURE OF ACCIDENT																					UNDTD																		

DUTY ON WHICH ENGAGED:

Solo flying practice.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft ground looped after landing.

DATE:

COMPOSITION:

LS/pss

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperienced pupil.~~

2. Stalling

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE