

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19																																																																																																																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	18																																																																																																																													
																	TECH.											DISOB.										NEG'NCE									INEXP'NCE								MISCEL.							INSTRUCT.						FLT. CONTR.					OTHERS				PRIMARY			FL. CONTRS.		MOV. SURFS.		STAB. SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UND'TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTRS.		MISCEL.		UND'TD		HAND O.		INSTS		WEATHER		DRKNS.		AL-G SURF.		OTHER		UND'TD		PRIMARY		TAXYING		LANDING		TAKE OFF		FLIGHT		STATRY		FATAL		INJ		3RD.		5		1	
TYPE OF A/C																	PILOT											OTHERS									AIRFRAME FAILURE																	ENGINE FAILURE																																																																																																							
CAUSES OF ACCIDENTS																																																																																																																																																													
UNIT																	13 S.F.T.S.											COM.									PLACE							DATE						TIME																																																																																																											
St. Hubert																	# 3									Main Aerodrome							22-9-42						1135																																																																																																																						
A/C TYPE																	Harvard 11											No.									2915							CRASH CAT.						SE			ME			DAY			NIGHT																																																																																																		
																	NAME											RANK									No.							DUTY						INJURIES						SERIOUS																																																																																																					
																	Brandenburg, J.H.											LAC									R137015							SP						Uninjured.						FATAL			INJURY																																																																																																		
																																																		CARD SERIAL No.																																																																																																											
																	TYPE A/F & ENGINE											No.									EXTENT OF DAMAGE							REPORT FORM						SERIAL No.						DATE			HOURS FLOWN BY PILOTS																																																																																																		
																	Harvard											2915									Slightly																			INST.			NIGHT			ON TYPE			TOTAL			LAST 6 MOS																																																																																									
																	Weap 4670/9282											Slightly																																																																																																																																	
																	SIGNAL No. & DATE											UNIT No. & DATE									COM. No. & DATE							REPORT						FILE			DATE																																																																																																								
																	A 421											22-9																																																																																																																																	
NATURE OF ACCIDENT																																																																																																																																																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	1																																																																																																																												

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Navigation exercise, 16.

OR COMMANDING OFFICER'S REPORT:

R.170 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil switched to empty tank instead of reserve and then forced landed on the aerodrome wheels up.

COMPOSITION:

LB/AOP/...

RECOMMENDATIONS:

PRIMARY CAUSE:

J. W. M.
Pupil throttled back to test horn. Throttle rod broke due to fault in metal.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pupil lectured on unnecessary forced landings.
Log Book endorsed and logged.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Wheels up forced landing.~~

RECORDED BY

DATE

CHECKED BY

DATE