

,))))))))))))))))))))))))))))	$\rightarrow \rightarrow \rightarrow$))))))))
(DUTY ON WHICH ENGAGED:	OR COMMANDING OFFICER'S REPORT:)
)		Taxiing at night.							γ
)		NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:		T	PET/E	Land Control of the C)
)		When taxiing at night AJ548 came	COMPOSITION:		1 CA /	PEIZ			}
		up from rear and taxied into AJ550			/CA/	XA)
)		in spite of brake being applied and engine switched off when AJ550 was)
)		noticed.	RECOMMENDATIONS:)
)									-
)		PRIMARY CAUSE:			x				•
) [.]		Collisions [9])
,		197	ACTION TAKEN:		•)
'			(A) DISCIPLINARY (B) TECHNICA	L (C) OTHER	₹)
,)
,)
,		SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
,		SESSIONAL CROSE ON CONTRIBUTING FACTORS:			_)
,					RECO	ORDED BY	Ì	DATE)
ļ '					==== =				
(R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41			CHEC	CKED BY	I	DATE)
L .	_))))))))) -))))))_