

CASPIR Aircraft Accident Cards

Serial: BW188

Title: North American Harvard Mk. II / 2A serial:BW188 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-September-30. Harvard s/n BW188. This accident involved 1 person. Florentsen F

Keywords: RAFHarvard ,BW188,41 SFTS,41 Service Flying Training School,Weyburn Aerodrome,1942-September-30,FlorentsenRCAF L20

Created: 1942-09-30

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#BW188>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Landing.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:
COMPOSITION:

Aircraft ground looped. after
landing.

15/1/53 ✓ R.170

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperience of pilot.~~

Swing

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C ground looped.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____