

DUTY ON WHICH ENGAGED:

Solo cross country.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Aircraft landed with undercarriage partly retracted. Ran off end of runway into soft ground where u/c retracted fully.

12/2/41

RECOMMENDATIONS:

PRIMARY CAUSE:

~~U/C motor cut out, failed to operate causing failure of entire electrical system and seized U/C motor preventing manual operation.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

Misc. Technical

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C landed with U/C partly retracted. Ran into soft ground and U/C retracted fully.~~
U/C defect 35

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____