



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying practice.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R.170

Starboard engine failed, and pilot forced landed. Undercarriage struck ground and made belly landing.

COMPOSITION:

*1st Lt. / 1st Lt. / 1st Lt.*

RECOMMENDATIONS:

PRIMARY CAUSE:

Failure of STD engine, electrical system and U/C.

*Forced Landing*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Nil.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Unable to maintain height on one engine, force landed.

*Engine Trouble - Accident*

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_