

TYPE OF ACCIDENT		PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE			
CAUSES OF ACCIDENTS		UNIT		COM.		PLACE		DATE		TIME	
		2 W. S. Calgary, Alta.		# 4		Main Aerodrome		21-9-42		1530	
		A/C TYPE		No.		CRASH CAT.		SE		ME	
		Fleet Fort II		3584		B		X		DAY NIGHT	
		NAME		RANK		No.		DUTY		INJURIES	
		Floyd, H.G.		GB		SGT		1386547		PP	
										SERIOUS	
										FATAL INJURY	
										CARD SERIAL No.	
		TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.	
		Fleet Fort 3584		2183/16001		Seriously		Seriously		DATE	
										HOURS FLOWN BY PILOTS	
										INST. NIGHT	
										ON TYPE TOTAL	
										DUAL SOLO DUAL SOLO	
										LAST 6 MOS.	
		SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE	
		Q 40		21-9						DATE	
										NATURE OF ACCIDENT	

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

 PRIMARY  
 UNDTD  
 AIRSCREW A.  
 ENG. CONTS.  
 MISCEL.  
 UNDTD  
 HAND. Q.  
 INSTS.  
 WEATHER  
 DRKNS.  
 ALG SURF.  
 OTHER  
 UNDTD  
 PRIMARY  
 TAXING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 3RD.  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100

 1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100

 TECH.  
 DISOB.  
 NEG NCE  
 INEXP NCE  
 MISCEL.  
 INSTRUCT.  
 FLT. CONTR.  
 OTHERS  
 PRIMARY  
 FL. CONTS.  
 MOV. SURFS.  
 STAB SURFS.  
 W. STRUTS  
 LAND GEAR  
 FLOATS  
 FUSE OR HULL  
 TAIL SKID OR W.  
 ENGINE MOUNT.  
 MISCEL.  
 UNDTD  
 PRIMARY  
 FUEL SYS.  
 COOL SYS.  
 IGNIT. SYS.  
 LUB'N SYS.  
 ENG. STR.  
 AIRSCREW A.  
 ENG. CONTS.  
 MISCEL.  
 UNDTD

 1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100

DUTY ON WHICH ENGAGED:

Solo on new type aircraft.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Port brake seized after alighting.  
Aircraft nosed over.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION:

1 M/A T O / 3 20

RECOMMENDATIONS:

Suggested that examinations be made of drums every 2 or 3 days when landings and taxiing has been done.

PRIMARY CAUSE:

~~Brake seizure.~~

*Other*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C overturned.~~

*Brake Failure*

RECORDED BY

DATE

CHECKED BY

DATE