

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																														
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																														
TECH.		DISOB.		NEG'NCE		INEXP'NCE		MISCEL.		INSTRUCT.		FLT. CONTR.		OTHERS		PRIMARY		FL. CONTRS.		MOV. SURFS.		STAB. SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SKID OR W.		ENGINE OR W.		MISCEL.		UNDTD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTRS.		MISCEL.		UNDTD		PRIMARY	
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																															
CAUSES OF ACCIDENTS																																																													
UNIT 145 (BR) Sqn.								COM. E.A.C.				PLACE R.C.A.F. Station Tor Bay																DATE 16-9-42				TIME 0945																													
Tor Bay								E.A.C.				R.C.A.F. Station Tor Bay																H.Q. FILE 1100-6-21																																	
A/C TYPE		Hudson						No. 781		CRASH CAT. B		SE		ME		DAY		NIGHT																																											
		Hudson						621-D		C				x		x																																													
NAME										RANK		No.		DUTY		INJURIES				SERIOUS																																									
Ross, L.T.										P/O		J9246		SP		Uninjured.				FATAL		INJURY																																							
Buchanan, M.D.										SGT		R100725		NAV		Uninjured.																																													
Butler, W.G.										SGT		798711		NAV		Uninjured.																																													
Hollinger L.A.										SGT		R95661		WAG		Uninjured.																																													
																				CARD SERIAL NO.																																									
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																	
												INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																											
Hudson		621		Slightly.								23 23		18 112		25 214																																													
P-39510/S39526 MIL.																																																													
Hudson		781		Seriously.																																																									
P28476/3085 S28280/3047 MIL																																																													
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																									
A 29 16-9																																																													
NATURE OF ACCIDENT																																																													

CAUSES
 MISCELLANEOUS
 FLIGHT
 STAGE OF

UNDTD
 PRIMARY
 HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UNDTD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.
 INJURY

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER H. J. S.

Taxiing out on taxi strip for patrol,

OR COMMANDING OFFICER'S REPORT:

P.170

Investigating Officer's Report

NATURE OF ACCIDENT AND STAGE OF FLIGHT: 621 DATE: 18-9-42

Collided with Hudson 781 parked
on taxi strip.

COMPOSITION:

P.O. J.B. Friedlander No. 5 (CAC) Det., Torbay

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Aircraft parked on taxi strip
and failure of pilot to have
airmen watching wing tips.
Error in judgement on part of
pilot.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

A/C in future to be parked at a safer distance on
strip to make more room for taxiing A/C. Also a
better system of signalling for wing tip guide men.
Pilot's Log Book endorsed "Error of Judgement"
Shop mule en-route to unit to assist in taxiing A/C
Enlarging taxi strip. Instructions issued to have
"Servicing Crew" assist in RECORDED BY DATE
directing aircraft.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~621 collided with 781 parked
on taxi strip.~~

Collisions

CHECKED BY

DATE