



DUTY ON WHICH ENGAGED:

Air test.

COURT OF INQUIRY, INVESTIGATING OFFICER

4043

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft being taxied too fast down tarmac was uncontrollable and struck parked aircraft.

DATE:

10/1/50

COMPOSITION:

10/1/50

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness, taxiing too fast.~~

*Others*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C being taxied struck parked A/C.~~

RECORDED BY

DATE

CHECKED BY

DATE