

CASPIR Aircraft Accident Cards

Serial: FE302

Title: North American Harvard Mk. IIB serial:FE302 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-November-07. Harvard II s/n FE302. This accident involved 1 person. Florentsen FJ

Keywords: RAFHarvard II,FE302,41 SFTS,41 Service Flying Training School,Rlg Halbrite,1942-November-07,FlorentsenRCAF L20

Created: 1942-11-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE302>

DUTY ON WHICH ENGAGED:

Precautionary landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Ground loop.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

DATE:

D.14.

COMPOSITION:

LS/PSS ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Inexperience of pupil pilot.~~

2. SWUNG.

②

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

Pilot being considered for wastage.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft ground looped. Pupil
was not quick enough in correct-
ing swing following landing.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____