

CASPIR Aircraft Accident Cards

Serial: FE344

Title: North American Harvard Mk. IIB serial:FE344 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-November-07. Harvard II s/n FE344. This accident involved 2 people. Cosgrove AJ, Potter JAJ

Keywords: RAFHarvard II,FE344,41 SFTS,41 Service Flying Training School,Weyburn,1942-November-07,Cosgrove,PotterRCAF L20

Created: 1942-11-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE344>

DUTY ON WHICH ENGAGED:

N/F Dual.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Immediately aircraft became air-borne starboard wing dropped. Corrective action by instructor failed to rectify.

DATE:

D.14.

COMPOSITION:

000/AOC/PCDM/I ✓

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

~~Inexperience on the part of the instructor.~~

14. Out of Control.

14

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor's log book endorsed. Instructor to be checked by visiting flight.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~a/c pulled off runway too soon by inexperienced pupil causing stall and dropping of wing.~~

RECORDED BY

DATE

CHECKED BY

DATE