

CASPIR Aircraft Accident Cards

Serial: FE314

Title: North American Harvard Mk. IIB serial:FE314 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1942-November-20. They are: Harvard II s/n FE349, Harvard II s/n FE314. This accident involved 2 people. Cooper CJ, Pardoe ACC

Keywords: RAFHarvard II,FE314,41 SFTS,41 Service Flying Training School,Aerodrome,1942-November-20,Cooper,PardoeRCAF L20

Created: 1942-11-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE314>

DUTY ON WHICH ENGAGED:

Solo night flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C FE349 taxied into A/C FE314.

DATE:

COMPOSITION:

D-14

MULT

TCA/PCT ✓

TCA/XA

RECOMMENDATIONS:

PRIMARY CAUSE: Carelessness.

~~Fast taxiing on part of pilot
of FE349.~~

9. COLLISIONS

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsement.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~FE349 taxied into FE314.~~

~~Burst port tire from sudden application
of brakes.~~

RECORDED BY

DATE

CHECKED BY

DATE