



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Routine low level ~~bombing~~ exercise. OR COMMANDING OFFICER'S REPORT:

INVESTIGATING OFFICER'S REPORT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

STBD engine failed and pilot states he could not maintain height on one engine, A/C force landed.

COMPOSITION:

Investigation shows that he hit a strawstack with his Stbd engine.

RECOMMENDATIONS:

*11/17/71  
1100-3267. No loss of life  
Investigation  
11/16*

*1106/102*

PRIMARY CAUSE:

~~UNAUTHORIZED LOW FLYING.~~

17 FORCED

LANDING  
17

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~ENGINE CUT OUT NECESSITATING FORCED LANDING.~~

~~STRUCK STRAW STACK.~~

26. ENGINE TROUBLE - ACCIDENT

26

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_