

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	8269
<b>Title:</b>	Avro Anson Mk. II serial:8269 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1942-November-21. Anson II s/n 8269. This accident involved 3 people. Cook NM, Donald JL, Hartman CL
<b>Keywords:</b>	RCAFAnson II,8269,8 BGS,8 Bomb & Gunnery School,4 Mile S Of West End Of Air Firing Range,1942-November-21,Cook,Donald,HartmanRCAF L20
<b>Created:</b>	1942-11-21
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8269">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8269</a>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Routine low level ~~bombing~~ exercise. OR COMMANDING OFFICER'S REPORT:

INVESTIGATING OFFICER'S REPORT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

STBD engine failed and pilot states he could not maintain height on one engine, A/C force landed.

COMPOSITION:

Investigation shows that he hit a strawstack with his Stbd engine.

RECOMMENDATIONS:

*1100-3260. No loss of life. Inventory to be made.*

PRIMARY CAUSE:

*1100/102*

~~UNAUTHORIZED LOW FLYING.~~

17 FORCED

*LANDING*  
*(17)*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~ENGINE CUT OUT NECESSITATING FORCED LANDING.~~

~~STRUCK STRAW STACK.~~

26. ENGINE TROUBLE - ACCIDENT

*(26)*

RECORDED BY

DATE

CHECKED BY

DATE