

DUTY ON WHICH ENGAGED:

Sequence 19.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

On starting up engine of aircraft,
Starboard hydraulic system failed
letting aircraft settle on ground.
Starboard undercarriage retracted.

DATE:

D.14.

COMPOSITION:

Proposed by [unclear]

RECOMMENDATIONS:

Thorough cockpit checks must be carried out prior
to and again after starting up the engines.

PRIMARY CAUSE:

~~Faulty cockpit check.~~

II. OTHERS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot legged.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Starboard undercarriage retracted.~~

33. *W/C DRILL - ON GROUND*

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____