



DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14

O FM / AOP / ES / PT / G / O / AMB ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Stbd. motor failed just after take-off. Pupil landed in field and ran into scrub.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Starboard motor failed just after take-off. Starboard gas cock incorrectly assembled.~~

15 FORCED LAND

15

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action being taken against mechanic who inserted gas cock wrongly, Pupil progress checked for reaction in emergencies.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Landed in field and ran into scrub.~~

26. ENGINE TROUBLE

26

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_