

32		31		30		29		28		27		26		25		24		23		22		21		20		19		18		17		16		15		14		13		12		11		10		9		8		7		6		5		4		3		2		1		18		17		16		15		14		13		12		11		10		9		8		7		6		5		4		3		2		1	
JU.		TECH.		DISOB.		NEG-NCE		INEXP NCE		MISCEL.		INSTRUCT.		FLT. CONTR.		OTHERS		PRIMARY		FL CONTRS.		MOV. SURFS.		STAB SURFS.		W. STRUTS		LAND GEAR		FLOATS		FUSE OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UND TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTRS.		UND TD		PRIMARY																																							
PILOT		OTHERS						AIRFRAME FAILURE												ENGINE FAILURE																																																																															
CAUSES OF ACCIDENTS																																																																																																			
UNIT		COM.			PLACE			DATE		TIME																																																																																									
11 E.F.T.S.		# 3			7 miles N.W. of M.A.			17-11-42		1320																																																																																									
Cap de la Mad.								H.Q. FILE		1100-45-25																																																																																									
A/C TYPE		No.			CRASH CAT.			SE		ME		DAY		NIGHT																																																																																					
Finch II		4525			C 3			x		x																																																																																									
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																																																																																					
Warriner, G.E.				SGT		R102520		FI		Nil				FATAL INJURY																																																																																					
Quigley, R.J.				CPL		R64051		PP		Nil																																																																																									
CARD SERIAL No.																																																																																																			
TYPE A/F & ENGINE				No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																					
Finch II 4525				NiL.										INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.																																																																											
Kinner 6090/1425				Serious														DUAL		SOLO		DUAL		SOLO																																																																											
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																																																																																			
A656 18-11																																																																																																			
NATURE OF ACCIDENT																																																																																																			

CAUSES  
MISCELLANEOUS  
STAGE OF FLIGHT

HAND Q.  
INSTS.  
WEATHER  
DRINKS.  
ALG SURF.  
OTHER  
UND TD  
PRIMARY  
TAXING  
LANDING  
TAKE-OFF  
FLIGHT  
STAT RV  
FATAL  
INJ  
3RD.  
INJ

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

**Dual instructional flight.**

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

**When carrying out a steep turn  
the engine suddenly stopped.  
The instructor carried out a  
successful forced landing**

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

**Engine seizure.**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Nil.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Successful forced landing carried  
out by instructor.**

RECORDED BY

DATE

CHECKED BY

DATE