

TYPE OF A/C		PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																					
TYPE OF ENGINE		UNIT 123 Squadron										COM. E.A.C.										PLACE Main Aerodrome Debort										DATE 23-11-44										TIME 2030																																																											
CATEGORY		Debort, N.S.										E.A.C.										Main Aerodrome Debort										H.Q. FILE 1300-AM889																																																																					
A/C TYPE		Lysander										No. 473 D										CRASH CAT. C 7										SE x										ME										DAY										NIGHT																																							
NAME		RANK										No.										DUTY										INJURIES										SERIOUS																																																											
TYPE A/F & ENGINE		No.										EXTENT OF DAMAGE										REPORT FORM										SERIAL No.										DATE										INST.										NIGHT										ON TYPE										TOTAL										LAST 6 MOS.									
Hudson		AM889										Serious										Pratt & Whitney										A203820/A203894										NIL.																																																											
SIGNAL No. & DATE		UNIT No. & DATE										COM. No. & DATE										REPORT										FILE										DATE																																																											
A 835		24-11										Other Signal from 31 O.T.U.																																																																																									
NATURE OF ACCIDENT																																																																																																					
STAGE OF FLIGHT																																																																																																					
MISCELLANEOUS CAUSES																																																																																																					
HANDQ.																																																																																																					
WEATHER																																																																																																					
DRKNS.																																																																																																					
ALG SURF.																																																																																																					
OTHER																																																																																																					
UND'TD																																																																																																					
PRIMARY																																																																																																					
TAXIING																																																																																																					
LANDING																																																																																																					
TAKE-OFF																																																																																																					
FLIGHT																																																																																																					
FATAL																																																																																																					
INJ.																																																																																																					
3RD. INJ.																																																																																																					

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Awaiting take-off on the runway.--  
Night flying circuits. -- 473 AM889

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

While waiting for take-off was hit  
by Lysander 473 of No. 123 Squadron  
which was engaged on night flying  
without prior authority from flying  
control Debert.

COMPOSITION:

RECOMMENDATIONS:

MULTI D-14

TCM/PCT

TCM/XH

PRIMARY CAUSE:

~~Carelessness on part of pilot  
of 473.~~

9 COLLISIONS

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~473 struck Hudson AM889 while  
taxiing.~~

RECORDED BY

DATE

CHECKED BY

DATE