

## CASPIR Aircraft Accident Cards

---

**Serial:** FE440

**Title:** North American Harvard Mk. IIB serial:FE440 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-December-26. Harvard II s/n FE440. This accident involved 1 person. Greene CE

**Keywords:** RAFHarvard II,FE440,41 SFTS,41 Service Flying Training School,Lang,1942-December-26,GreeneRCAF L20

**Created:** 1942-12-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE440>



DUTY ON WHICH ENGAGED:

Formation flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot attempting a forced landing stalled aircraft and crashed. Pilot apparently thought his airspeed was excessive, throttled back causing A/C to sink and contact ground. Engine would not respond to throttle probably due to bent prop.

DATE:

D-14

COMPOSITION:

FB/PSM/PCDE/ES/NY/MZ ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment.~~

FORCED LANDING. (17)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Force landed, stalled and crashed.~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_