

DUTY ON WHICH ENGAGED:

Transport to relief aerodrome.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Starboard engine misfired and lost power. Pilot retracted undercarriage and made emergency landing 200 yards from end of runway.

DATE:

COMPOSITION:

VAD
D-14
R/M/ES/DM/M/I/00-1-2

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Failure of Starboard engine on take-off. Probable carburettor trouble.~~

17. FORCED LANDING

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Emergency landing with U/C up.~~

26. ENGINE TROUBLE-

ACCIDENT.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____