

DUTY ON WHICH ENGAGED:

Night flying training. A/C taxiing preparatory to take-off.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft taxiing north along short piece of unlighted taxi strip and sank into newly constructed unlighted ditch.

DATE:

COMPOSITION:

TBG/PCT/~~EST~~^{D-14}/XGM/XLP

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Pilot confused by different rows of lights mistook East-West runway for taxi strip.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot "logged".

11. OTHERS

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C ran into ditch along side runway.~~

RECORDED BY

DATE

CHECKED BY

DATE