

CASPIR ARCHIVAL METADATA

Serial:	5814
Title:	de Havilland Moth, Tiger I serial:5814 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1942-December-11. Tiger Moth s/n 5814. This accident involved 1 person. Berryman RW
Keywords:	RCAFTiger Moth ,5814,15 EFTS,15 Elementary Flying Training School,No 3 Bombing Range,1942-December-11,BerrymanRCAF L20
Created:	1942-12-11
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5814

DUTY ON WHICH ENGAGED:

Ferrying aircraft.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot could not locate aerodrome.
Pilot attempted forced landing on
road. Aircraft struck soft snow
and ground looped into ditch.

DATE:

COMPOSITION:

FB/PCN ✓

D-14

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness on part of pilot.~~

2. Swung.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Endorsed log book for "Gross Carelessness".

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C landed and struck soft snow
and ground looped into ditch.~~

RECORDED BY

DATE

CHECKED BY

DATE