



DUTY ON WHICH ENGAGED:

Cross country solo.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C 3089 taxied to the line into parking place, Stbd wing of 3089 struck the pitot head of A/C AH185.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Error in judgment on part of pilot and inexperienced groundsmen.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot and groundsmen personally admonished by Chief Instructor and given extra duties.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C 3089 taxied into AH185.

RECORDED BY

DATE

CHECKED BY

DATE