

CASPIR Aircraft Accident Cards

Serial: AJ947

Title: North American Harvard Mk. II / 2 serial:AJ947 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-January-07. They are: Harvard II s/n 2880, Harvard II s/n AJ947. This accident involved 2 people. Lakin JHW, Staines GA

Keywords: RAFHarvard II,AJ947,41 SFTS,41 Service Flying Training School,Aerodrome,1943-January-07,Lakin,StainesRCAF L20

Created: 1943-01-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ947>

DUTY ON WHICH ENGAGED:

Taxiing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Harvard AJ947 taxied into Harvard 2880 which was being run up.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~hitting other aircraft.~~

G. Callahan

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log. book endorsed. Grounded in accordance with T.C. I'S. wastage action being taken.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Carelessness, failure to release brakes correctly, or possible temporary sticking brake.~~

RECORDED BY

DATE

CHECKED BY

DATE