

CASPIR Aircraft Accident Cards

Serial: FE326

Title: North American Harvard Mk. IIB serial:FE326 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-08. Harvard II s/n FE326. This accident involved 1 person. Reid JW

Keywords: RAFHarvard II,FE326,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-January-08,ReidRCAF L20

Created: 1943-01-08

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE326>

DUTY ON WHICH ENGAGED:

Forced landing practices.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft landed with undercarriage retracted. Pilot tested horn which did not sound, also failed to notice Red from A.C.P.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~34. Wheels up landing.~~

7. Other

(7)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Gross carelessness. Faulty cockpit drill.~~

32 *1/6 Drill - in* (32)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____