

CASPIR Aircraft Accident Cards

Serial: FE303

Title: North American Harvard Mk. IIB serial:FE303 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-13. Harvard II s/n FE303. This accident involved 2 people. Isaacs LC, Nairn GDT

Keywords: RAFHarvard II,FE303,41 SFTS,41 Service Flying Training School,Weyburn,1943-January-13,Isaacs,NairnRCAF L20

Created: 1943-01-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE303>

DUTY ON WHICH ENGAGED:

Instrument flying. Take-offs.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Starboard wing dropped . Instructor
overcorrected.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

DATE:

COMPOSITION:

PCDM/I



RECOMMENDATIONS:

PRIMARY CAUSE:

14. Misuse of controls.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

High wind.

RECORDED BY

DATE

CHECKED BY

DATE