

CASPIR Aircraft Accident Cards

Serial: AH190

Title: North American Harvard Mk. II serial:AH190 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-29. Harvard II s/n AH190. This accident involved 2 people. Beardsall GJ, Demades D

Keywords: RAFHarvard II,AH190,41 SFTS,41 Service Flying Training School,Weyburn,1943-January-29,Beardsall,DemadesRCAF L20

Created: 1943-01-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AH190>

DUTY ON WHICH ENGAGED:

Instrument flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

✓ D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Pupil recovering from spin under hood caused instructors left shoulder to force against panel of coupe top. Panel forced out causing damage to tail unit.

RECOMMENDATIONS:

PRIMARY CAUSE:

57* ~~Miscellaneous.~~

(18)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

18. Misc. Technical

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Violent recovery from P.I. spin.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____