

CASPIR Aircraft Accident Cards

Serial: FP774

Title: Avro Anson Mk. II serial:FP774 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-03. Anson II s/n FP774. This accident involved 2 people. Coulson JR, Shean HJ

Keywords: RAFAnson II,FP774,33 SFTS,33 Service Flying Training School,Aerodrome,1943-January-03,Coulson,SheanRCAF L20

Created: 1943-01-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP774>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Solo cross country training flight.

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LAC/REDUF/VEDL/XCA

COMPOSITION:

Returning from cross country flight
pilot failed to lower undercarriage.

Pilot handed over to navigator who
flew from instructor's seat as pilot's

RECOMMENDATIONS:

hands were numb with cold from
making up his log.

PRIMARY CAUSE:

~~34. Wheels up landings.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) 168 hrs. detention. Grounded for 1 month in
accordance with No. 2 T.C. order and to be
permanent A.C.P.'s for three weeks.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Cold weather.~~ Aerodrome control pilot
failed to fire red very cartridge.

RECORDED BY _____ DATE _____

32. 1/6 Drill - in air

CHECKED BY _____ DATE _____