

ACCIDENT CLASSIFICATION												
UNIT 33 S.F.T.S. Carberry		COM. 2	PLACE RI Petrel			DATE 5-1-43	TIME 1645		COMMAND			
A/C TYPE ANSON II		NO. 11201		CRASH CAT. "D"	H.O. FILE 1100-112-01							
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH			
Herbert, P.H.		F/O	125477	FI	Uninj.		NO.	DATE				
Hicks, L.H.		LAC	1587948	PP	Uninj.		A.2	6-1				
							D 14 (REVISED)		STAGE OF FLIGHT			
							NO.	CHECKED				
							1		INJURY			
							#3					
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				CATEGORY				
Jacobs L6MB		17677, 9050 Nil 25067/9437slightly.		INST.	NIGHT	ON TYPE						TOTAL
						SOLO	DUAL	SOLO	DUAL	RAF		
				64	151	362	-	1275	151			
				8	5	2	12	33	54	M		
ACCIDENT CLASSIFICATION												

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Instruction. -Single engine flying
and approaches.

NATURE OF ACCIDENT:

Nil

After practicing single engine fly-
ing and approaches a/c was on final
part of approach to land with stbd
throttle fully closed when smoke was
seen to appear from stbd engine. Stbd
engine caught fire after landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

501/25/1000/L/AE/65

CLASSIFICATION:

~~43. Fire after landing.~~

7. Others

(7)

SECONDARY OR CONTRIBUTORY FACTORS:

21. Fire In engine only.

(31)

ACTION TAKEN: