



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

Starting engine.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

TCA/PCT  
MA/XA

D-14

COMPOSITION:

Engine of aircraft Tiger Moth 8912 started with high RPM. Jumped left check and swung 180 degrees into Harvard 2888 from 6 S.F.T.S. Dursville, Tiger Moth 8912 belonging to 12 E.F.T.S.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other A-C.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed, and reprimanded.

*9. Collision*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Tiger Moth Swung into Harvard 2888 which was parked. Misuse of throttle.~~

RECORDED BY

DATE

CHECKED BY

DATE