



DUTY ON WHICH ENGAGED:

7854 Night Flying Test.  
8825 Circuits and landing.

COURT OF INQUIRY, INVESTIGATING OFFICER

*MULT*

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

7854 was parked prior to take off  
and 8825 taxied into it.

DATE:

COMPOSITION:

*TCA/PT ✓*  
*MA/SA*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

*9. Collision*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) LAC Brady awarded 14 days C.B. Log Book  
endorsed for "Carelessness". Grounded one  
month and transferred to Course 73.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Carelessness on part of LAC Brady  
in not keeping sharp enough look-out  
while taxiing.~~

RECORDED BY

DATE

CHECKED BY

DATE