

CASPIR Aircraft Accident Cards

Serial: 3841

Title: North American Harvard Mk. II serial:3841 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-February-01. Harvard II s/n 3841. This accident involved 2 people. Ellis AJ, Papworth WGM

Keywords: RAFHarvard II,3841,41 SFTS,41 Service Flying Training School,Talmage,1943-February-01,Ellis,PapworthRCAF L20

Created: 1943-02-01

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3841>

DUTY ON WHICH ENGAGED:

Low flying exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Approaching low flying area a/c
lost height. Pilot omitted to
maintain temperatures. Engine
faltered in picking up and wing
hit top of tree.

RECOMMENDATIONS:

PRIMARY CAUSE:

32. Pilot error.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pilot failed to maintain sufficient
engine temperature.

RECORDED BY

DATE

CHECKED BY

DATE