

## CASPIR Aircraft Accident Cards

---

**Serial:** FE316

**Title:** North American Harvard Mk. IIB serial:FE316 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-February-05. Harvard II s/n FE316. This accident involved 2 people. Barton EA, Heath C

**Keywords:** RAFHarvard II,FE316,41 SFTS,41 Service Flying Training School,Aerodrome,1943-February-05,Barton,HeathRCAF L20

**Created:** 1943-02-05

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE316>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Instrument flying.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

D-14

Overshot slightly, brakes failed to hold on compacted snow, A/C ran past boundary into snow and turned on to its nose.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

29. Overshooting runway.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Error of Judgment".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Error of judgment.

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_