

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ933

**Title:** North American Harvard Mk. II / 2A serial:AJ933 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1943-February-05. They are: Harvard II s/n FE346, Harvard II s/n AJ933. This accident involved 1 person. Alexander GJF

**Keywords:** RAFHarvard II,AJ933,41 SFTS,41 Service Flying Training School,Aerodrome,1943-February-05,AlexanderRCAF L20

**Created:** 1943-02-05

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ933>



DUTY ON WHICH ENGAGED:

Taxiing A/C.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil pilot taxiing towards parked A/C, applied brakes and skidded into parked Harvard AJ933.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

3. Hitting other A/C.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Action under T.C.I. 3/16. Log book endorsed. Ordered stoppage of pay to the extent of \$5. being half of the cost of damage to A/C concerned.

NOTE: Stoppage of pay contrary to existing regulations. A.O.C. asked to consider remittance of amount Letter 794-A-367 (D of P) (P.1) 8th March, 1943.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Carelessness on part of pilot.  
Fast taxiing.

RECORDED BY

DATE

CHECKED BY

DATE