

## CASPIR Aircraft Accident Cards

---

**Serial:** FP706 (formerly 706)

**Title:** Avro Anson Mk. II serial:FP706 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-February-16. Anson II s/n FP706 (formerly 706). This accident involved 2 people. Hern-black FL, Lawrence WP

**Keywords:** RCAFAnson II,FP706 (formerly 706),9 SFTS,9 Service Flying Training School,Aerodrome,1943-February-16,Hern-black,LawrenceRCAF L20

**Created:** 1943-02-16

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP706>



DUTY ON WHICH ENGAGED:

**Sequence 7.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**A/C swung off runway striking snowbank.**

DATE:

COMPOSITION:

2 5/17 = 2/17

RECOMMENDATIONS:

PRIMARY CAUSE:

~~1. Swinging~~

2. Swung

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Pilot's log book endorsed.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Failure of instructor to take over in sufficient time to avoid swing.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_