

CASPIR Aircraft Accident Cards

Serial: 3898

Title: de Havilland Moth, Tiger I serial:3898 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-February-07. Tiger Moth s/n 3898. This accident involved 1 person. Bond IB

Keywords: RCAF Tiger Moth ,3898,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-February-07,Bond RCAF L20

Created: 1943-02-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#3898>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Taking off into wind.

OR COMMANDING OFFICER'S REPORT:

4 D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/c undershot rolled section of field and landed in deep snow causing a/c to overturn .

COMPOSITION:

LU/PS- / ~~---~~
XGM

RECOMMENDATIONS:

PRIMARY CAUSE:

~~30. Undershooting runway.~~

3. Undershot

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Recommended to the Department of Transport that better Boundary markers be obtained.

Boundary markers in the form of red flags to be placed around west field.

Pupil placed on charge. Dismissed. Advised to use more caution in future.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Neglect and carelessness on part of student.~~

~~Light condition rendering boundaries obscure.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____