

## CASPIR Aircraft Accident Cards

---

**Serial:** 3623

**Title:** Fleet Fort serial:3623 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-February-10. Fleet Fort 60K s/n 3623. This accident involved 2 people. Fewtrell GH, Muller JR

**Keywords:** RCAF Fleet Fort 60K,3623,3 WS,3 Wireless School,Aerodrome,1943-February-10,Fewtrell,MullerRCAF L20

**Created:** 1943-02-10

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3623>



DUTY ON WHICH ENGAGED:

W/T exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C nosed up while taxiing damaging wing and propeller.

COMPOSITION:

D-14  
M/PA/PA/XG/PA

RECOMMENDATIONS:

PRIMARY CAUSE:

~~35. Cross winds and gusts.~~

11. Other

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER  
Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Strong wind. Runway was icy with snow drifts 2" to 6" deep.~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_