



DUTY ON WHICH ENGAGED:

Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Starboard engine failed while taking off - a/c swung and hit ground heavily.

D-14  
CS/PSO/ES/1M/M/O/WIE

RECOMMENDATIONS:

Pupil be given further instruction in the event of an engine failure on take off.

PRIMARY CAUSE:

1) Engine failure.

2. Swung

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Failure of stbd engine, pupil's failure to correct the subsequent swing.

RECORDED BY

DATE

CHECKED BY

DATE