

CASPIR Aircraft Accident Cards

Serial: AS706

Title: Airspeed Oxford Mk. II serial:AS706 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-February-27. Oxford II s/n AS706. This accident involved 1 person. Taylor AF

Keywords: RAFOxford II,AS706,35 SFTS,35 Service Flying Training School,Hamlin R1,1943-February-27,TaylorRCAF L20

Created: 1943-02-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS706>

DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot undershot boundary during precautionary landing practice touched down in deep snow and a/c overturned.

DATE:

LU/PSU

D-14

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~30. Undershooting runway.~~

3. Undershot

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further instruction to be given.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot error, undershot and overturned in deep snow.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____