

CASPIR Aircraft Accident Cards

Serial: 3621

Title: Fleet Fort serial:3621 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-February-28. Fleet Fort 60k II s/n 3621. This accident involved 2 people. Sinclair AJ, Wood DL

Keywords: RCAFFleet Fort 60k II,3621,3 WS,3 Wireless School,Stevenson Field
Winnipeg,1943-February-28,Sinclair,WoodRCAF L20

Created: 1943-02-28

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3621>

DUTY ON WHICH ENGAGED:

Wireless schools.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft nosed up while taxiing
in gusty wind, damaging propellor.

DATE:

COMPOSITION:

TN/ANT/PET/WWG

RECOMMENDATIONS:

PRIMARY CAUSE:

~~35. Cross winds and gusts.~~

11. Other

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilots have been advised to remain where they are and
be hauled in by tractor, if they feel there is any danger
of nosing up whilst taxiing.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Strong wind caused A/C to swing~~

RECORDED BY

DATE

CHECKED BY

DATE