

TYPE OF ACCIDENT		PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE																					
CAUSES OF ACCIDENTS												HAND Q.																			
UNIT		COM.		PLACE				DATE		TIME		PRIVATE																			
8 B & G		4		1/2 mi. S of aerodrome				18-2-43		1100		✓																			
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																			
Bolingbroke		9974		B				X		X																					
NAME			RANK	No.	DUTY	INJURIES				SERIOUS																					
Simpson, W.C.R.			F/S	R103671	P.	Uninj.				FATAL INJURY																					
Hutton, F.C.W.			LAC	AUS414036	AG	Uninj.																									
Johnston, A.M.			LAC	R138020	AG	Uninj.																									
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS																								
Bolingbroke 9974							INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																		
Mercury XV									DUAL SOLO		DUAL SOLO																				
Port S4782																															
Stbd S4796																															
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		STAGE OF FLIGHT																			
A210 18-2-43												LANDING TAKE-OFF FLIGHT STATRY FATAL INJ. 3RD. INJURY																			
NATURE OF ACCIDENT																															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

DUTY ON WHICH ENGAGED:
Routine gunnery flight.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Port motor failed on landing approach
u/c retracted and forced landed
in soft field.

DATE:
COMPOSITION:

12 PM / 10 / ES / [signature] / [signature] / [signature]

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~

17. Forced Landing

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

16 Engine Trouble - Accident

RECORDED BY

DATE

CHECKED BY

DATE