



DUTY ON WHICH ENGAGED:

Solo flying training

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine failure after takeoff  
Struck telephone post while  
making forced landing.

DATE:

COMPOSITION:

*406*  
*OTM / [unclear] / [unclear] / [unclear]*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~13. Engine failure.~~

*6. Collision*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*Nil.*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~The engine was not overhauled, worn  
before take off.~~

*Engine Trouble - Accident*

RECORDED BY

DATE

CHECKED BY

DATE