

CASPIR Aircraft Accident Cards

Serial: 2793

Title: North American Harvard Mk.II serial:2793 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-March-02. Harvard II s/n 2793. This accident involved 1 person. Whiteley A

Keywords: RAFHarvard II,2793,34 SFTS,34 Service Flying Training School,Aerodrome,1943-March-02,WhiteleyRCAF L20

Created: 1943-03-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2793>

DUTY ON WHICH ENGAGED:

Solo practice landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14



NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C landed with U/C retracted.

**U/C warning system defective
in the air.**

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

33. Technical defect.

17. Forced Landing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

34. Wheels up landing.

35. U/C Defect

RECORDED BY

DATE

CHECKED BY

DATE