

CASPIR Aircraft Accident Cards

Serial: FE443

Title: North American Harvard Mk. IIB serial:FE443 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-March-08. Harvard II s/n FE443. This accident involved 1 person. Arnold D

Keywords: RAFHarvard II,FE443,41 SFTS,41 Service Flying Training School,Aerodrome,1943-March-08,ArnoldRCAF L20

Created: 1943-03-08

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE443>

DUTY ON WHICH ENGAGED:

Solo circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C undershot flarepath and
landed in uncompacted snow turning
completely over.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~30. Undershooting runway, during
night flying practice.~~

3. Undershot

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~32. Pilot error.~~

~~37. Overturning.~~

~~Increasing wind strength.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____