

CASPIR Aircraft Accident Cards

Serial: AJ916

Title: North American Harvard Mk. II serial:AJ916 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-March-10. Harvard II s/n AJ916. This accident involved 1 person. Haigh GM

Keywords: RAFHarvard II,AJ916,41 SFTS,41 Service Flying Training School,Aerodrome,1943-March-10,HaighRCAF L20

Created: 1943-03-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ916>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Precautionary and forced landing exercises.

OR COMMANDING OFFICER'S REPORT:

✓ D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C overshoot runway, hit snowbank and overturned.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~29. Overshooting runway.~~

~~Bad visibility & approaching darkness.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

~~Rapid deterioration of weather & extremely~~

~~low visibility made conditions almost impossible for pilot to see, Nil.~~

~~either signal area or illuminated~~

~~landing "T". Semi blizzard con-~~

~~ditions existed. Pupil made a slightly down wind~~

~~SECONDARY CAUSE OR CONTRIBUTING FACTORS: landing & overshoot.~~

~~47. Weather.~~

~~37. Overturning.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____